AD A 0 6 1 2 4 8 RADCOM -12256 CAL REP 12256 Tago TO ASSIST IN ESTABLISHING SOUNDNESS REQUIREMENTS WALTER F. HULF. AND NELVIN V. PHYTILA

> U.S. ARMY TANK-AUTOMOTIVE RESEARCH AND DEVELOPMENT COMMAND Warren, Michigan 48090

Approved for public release; distribution unlimited.

78 11 02 010 AB

TECHNICAL REPORT NUMBER 12256

DEVELOPMENT OF QUALITY ASSURANCE TRAINING MANUAL TO ASSIST IN ESTABLISHING SCURCHESS REQUIREMENTS FOR ALUMINUM AND STEEL CASTINGS

BY

WALTER F. WULF AND MELVIN V. PHYTILA SALVATORE B. CATALANO AND DON MATICHUK

August 1978

ANNUR, MATERIAL APPLICATION AND TECHNOLOGY FUNCTION

ABSTRACT

Samples of aluminum and steel casting flaws most commonly experienced in production were selected to be radiographed in order to develop quantitative and descriptive picture images of various radiographic reference standards. Graphic illustrations of flaw size and flaw distribution for various radiographic reference standards were depicted by using radiographs and associated cross-sectional photo-macrographs. These graphic illustrations of radiographic levels of acceptance will provide meaningful design criteria for establishing realistic standards of acceptance for new material applications. This report also furnishes operational guidance to quality assurance and radiographic personnel in their normal on-the-job duties.




TABLE OF CONTENTS

	PAGE NO
Abstract	1
List of Charts and Figures	111
Introduction	1
(bject	1
Summery	1
Conclusions	1
Test Heterials	2
Test Equipment	2
Test Procedure	2
Results and Discussions	3
Distribution List	49
Form DD 1473	48

LIST OF CHARTS AND FIGURES

STEEL CASTING FLAWS

FIGURE NO.		PAGE NO.
1	Evaluation of Gas Porosity in Cast Steel	5
2	Evaluation of Gas Porosity in Cast Steel	6
3	Evaluation of Sand and Slag Inclusions in Cast Steel	7
4	Evaluation of Sand and Slag Inclusions in Cast Steel	8
5A	Radiographic Image of Dendritic Shrinkage in Cast Steel 2 Inches Thick	9
58	Evaluation of Dendritic Shrinkage in Cast Steel 2 Inches Thick	10
64	Radiographic Image of Internal Shrinkage in Cast Steel	11
6.0	Evaluation of Internal Shrinkage in Cast Steel	12
7A	Radiographic Image of Dendritic Shrinkage in Cast Steel 1-3/4 Inches Thick	13
78	Evaluation of Dendritic Shrinkage in Cast Steel 1-3/4 Inches Thick	14
88	Radiographic Image of Dendritic Shrinkage in 2-1/2" Thickness of Steel	15
88	Macrograph of Casting Cross-Section Re- vealing Severity and Location of Shrinkage Condition (Shown in Fig. 8A)	16
94	Radiographic Image of Dendritic Shrinkage in Cast Steel 2 Inches Thick	17
98	Macrographs of Casting Cross-Sections Revealing Severity and Location of Shrink Condition (Shown in Fig 9A)	18 1 9e
10	Evaluation of Sponge Shrinkage in Cast Steel 1-1/2 Inches Thick	19

LIST OF CHARTS AND FIGURES

FIGURE NO.	(65.61.61.61.61.61.61.61.61.61.61.61.61.61.	PAGE NO.
11A	Radiographic Image of Sponge Shrinkage in Cast Steel T-1/2 Inches Thick	20
113	Evaluation of Sponge Shrinkage in Cast Steel 1-1/2 Inches Thick	21
ASI	Hot Tears	22
128	Evaluation of Hot Tear in Cast Steel 2-1/2 Inches Thick	23
13A	Evaluation of Hot Tear in Cast Steel 2-1/2 Inches Thick	24
132	Evaluation of Hot Tear in Cast Steel 2-1/2 Inches Thick	25
	ALUMINUM CASTING FLAWS	
14	Evaluation of Gas Holes in Cast Alu- minum	27
1.8	Evaluation of Gas Holes in Cast Alu- minum	28
24	Evaluation of Gas Porosity-Round in Cast Aluminum	29
2В	Evaluation of Gas Porosity-Round in Cast Aluminum	30
3A	Evaluation of Gas Porosity-Round in Cast Aluminum	31
3В	Evaluation of Gas Porosity-Round in Cast Aluminum	32
44	Evaluation of Gas Porosity-Round in Cast Aluminum	33
4B	Evaluation of Gas Porosity-Round in	34

LIST OF CHARTS AND FIGURES

(Continued)

FIGURE NO.		PAGE NO
5A	Evaluation of Gas Porosity-Elongated in Cast Aluminum	35
58	Evaluation of Gas Porosity-Elongated in Cast Aluminum	36
6 A	Evaluation of Gas Porosity-Elongated in Cast Aluminum	37
6B	Evaluation of Gas Porosity-Elongated in Cast Aluminum	38
7 A	Evaluation of Grain Boundary Shrinkage in High Strength Cast Aluminum	39
7B	Evaluation of Grain Boundary Shrinkage in High Strength Cast Aluminum	40
8	Evaluation of Cavity Type Shrinkage in Cast Aluminum	41
9	Evaluation of Cavity Type Shrinkage in Cast Aluminum	42
10 A	Evaluation of Sponge Shrinkage in Cast Aluminum	43
10B	Evaluation of Sponge Shrinkage in Cast Aluminum	44
11A	Evaluation of Sponge Shrinka; in Cast Aluminum	45
11B	Evaluation of Sponge Shrinkage in Cast Aluminum	46
12	Evaluation of Foreign Material in Cast Aluminum	47
13	Evaluation of Foreign Material in Cast Aluminum	48

INTRODUCTION

Present soundness requirements for many military castings are being specified according to severity levels listed in various specifications. Standards are selected on the basis of their numerical rating, or as specified in a related specification without serious consideration of the type and degree of flaw permitted for each grade level. It was originally intended that reference radiographs be used to categorize designated standards according to the stress requirements of the casting. With this procedure many castings are produced to a greater soundness requirement than necessary; conversely, this procedure is too lenient for other highly critical castings and ultimately creates service problems.

In accordance with project authorization from U.S. Army Materials and Mechanics Research Center, the task of compiling a flaw correlation document was established under the Materials Testing Technology Program. The effort was determined necessary to greatly assist the human judgement presently involved in designating casting soundness requirements.

OBJECT

The object of this task is to provide a document which illustrates flaw correlation with radiographic images to assist design engineers in the proper selection of casting soundness requirements.

SUMMARY

Typical flaw specimens of varying severity levels, presently encountered in aluminum and steel castings, were selected from representative components obtained from government and commercial sources. Flaw severity levels were graded radiographically to existing military and ASTN reference standards and categorized according to casting size and thickness. Photo-macrographs of flaw cross-sections were correlated with radiographic images to illustrate the actual relationship of flaw size to the casting area under evaluation.

CONCLUSIONS

The completion of this document provides design engineers with flaw correlation data which will assist in more accurately selecting radiographic soundness requirements on future castings. This document will also furnish operational guidance to quality assurance and radiographic personnel in their normal on-the-job duties.

TEST MATERIALS

- 1. Scrapped steel armor castings.
- 2. Scrapped aluminum castings of 355, 356 and special ini-strength Kaiser KO1 alloy.
- Industrial x-ray film of various sizes, medium grain, fine grain, and extra-fine grain,
- 4. Commercial photographic copy film, size 4 x 5 inches.
- 5. Photographic projection print paper.

TEST EQUIPMENT

- 1. Industrial x-ray machine, 1000KVP, 3MA capacity
- 2. Industrial x-ray machine, 250KVP, 10MA capacity
- 3. Industrial x-ray machine, 140KVP, 2MA capacity
- 4. Industrial x-ray machine, 25KYP, 5MA capacity
- 5. Commercial 4 x 5 inch View camera
- 6. Commercial 4 x 5 condenser type photographic enlarger
- 7. Photographic reproduction printing equipment
- 8. Lithographic printing equipment

TEST PROCEDURE

- 1. The procedure followed during the program was as follows:
 - a. Radiographic evaluation
 - b. Metallographic evaluation
 - c. Selection of standards for flaw correlation
 - d. Reproduction of selected standards

2. Following is a brief description of each procedure:

a. Radiographic evaluation:

Radiography of approximately 20 each aluminum and steel armor castings was performed in accordance with MIL-STD-453(1), dated 4 September 1963 (Radiographic Inspection). A minimum quality level of 2-IT, representing 1.4 percent sensitivity was maintained for all exposures. Several x-ray machines and a variety of radiographic exposure techniques were employed.

b. Metallographic evaluation:

Cross-sections were extracted from the selected specimens of most flaw types for verification of radiographic evaluation. Photo-macrographs were made of typical flaw conditions for correlation with reference standards.

c. Selection of standards for flaw correlation:

Grading of standards for flaw correlation were based on existing military and ASTM reference standards. Two levels of severity and in some flaws special gross conditions were selected to correlate the radiographic image with the flaw cross-sectional area.

d. Reproduction of selected standards:

The original radiographs were photographically reproduced utilizing a conventional 4 x 5 inch view camera to copy the radiographic image as viewed with an eleven-tube flourescent illuminator. Since photographic printing papers do not have the latitude of x-ray film, projection prints were made to allow the control necessary to obtain an authentic reproduction. Two methods of final reproduction were used in this document. The aluminum standards were reproduced by the photographic method; however, due to the exceptionally high cost of photographic reproduction, the steel standards were reproduced by the lithographic method.

RESULTS AND DISCUSSIONS

The lack of flaw correlation data has led to a questionable procedure of specifying radiographic soundness requirements according to severity levels listed in specification without adequate radiographic and pictorial illustrations. The illustrated correlation data contained in

Figures 1 through 13 will enable recognition of flaw sizes and distribution as compared to casting cross-sectional appearance and assist in establishing more realistic standards of acceptance by design engineers and quality assurance personnel. This should ultimately result in greater reliability of aluminum and steel armor castings.


STEEL CASTING FLAWS

Radiographic image of gas porosity. Severity level shown compares with the following:

ASTM--E-446 -- Grade 2

ASTM-E-186 - Grade 2

MIL—R—11469 — Acceptance is based on pore size and casting thickness. Amount shown meets Std. 2 for 1", and Std. 1 for 2" thickness.



Macrograph of partial casting cross section showing normal location of porosity near the surface. (unetched, actual size)

EVALUATION OF GAS POROSITY IN CAST STEEL



Radiographic image of gas porosity. Severity level shown compares with the following:

ASTM—E-446 — Grade 4 ASTM—E—186 — Grade 4

MIL—R—11469 — Acceptance is based on pore size and casting thickness. Amount shown meets Std. 3 for 1", and Std. 2 for 2" thickness.



Macrograph of partial casting cross section showing normal location of porosity near the starface. (unetched, actual size)

EVALUATION OF GAS POROSITY IN CAST STEEL



Radiographic image of inclusions. Severity level shown compares with the following:

ASTM—E-446 — Grade 2 ASTM—E-186 — Grade 2

MIL—R—11469 — Acceptance based on inclusion size and casting thickness. Amount shown meets Std. 2 for 1", and Std. 1 for 2" thickness.



3

Macrograph of partial casting cross section showing normal location of inclusions near the surface. (unetched, actual size)

EVALUATION OF SAND AND SLAG INCLUSIONS IN CAST STEEL




Radiographic image of inclusions. Severity level shown compares with the following:

ASTM-E446 - Grade 5

ASTM-E186 - Grade 4

MIL—R—11469 — Acceptance based on inclusion size and casting thickness. Amount shown meets Std. 4 for 1" and Std. 3 for 2" thickness.




Macrograph of partial casting cross section showing normal location of inclusion near the surface. (unetched, actual size)

EVALUATION OF SAND AND SLAG INCLUSIONS IN CAST STEEL

FIG. 4

SHRINKAGE — (DENDRITIC)



RADIOGRAPHIC IMAGE OF DENDRITIC SHRINKAGE IN CAST STEEL 2 INCHES THICK.


EVALUATION INCLUDED IN FIG, 5B.

Fig. 5A

EVALUATION OF FIG. 5A


Severity level of the shrinkage shown in Fig. 5A compares with the following:

ASTM—E—446 — Type CA — Grade 3 ASTM—E—186 — Type I — Grade 3 MIL—R—11469 — Type B — Std 2



Macrograph of casting cross section AA, shown in Fig 5A, revealing severity and location of the shrinkage condition. (unetched, actual size)

EVALUATION OF DENDRITIC SHRINKAGE IN CAST STEEL 2 INCHES THICK



RADIOGRAPHIC IMAGE OF INTERNAL SHRINKAGE IN CAST STEEL.

EVALUATION INCLUDED IN FIG. 6B.


Fig. 6A

EVALUATION OF FIG. 6A

Severity level of shrinkage shown in Fig. 6A compares with the following:

SECT AA CAVITY ASTM—E—446 — Fails to meet any grade ASTM—E—186 — Not applicable, too thin MIL—R—11469 — Std. 5 (judged as gas)

SECT BB & CC ASTM-E-446 - Type CA - grade 3
ASTM-E-186 Not applicable, too thin
MIL-R-11469 - Type C - Std. 2









SECTION—CC

Marcographs of casting cross sections, shown in Fig 6A, revealing severity and and location of shrinkage condition. (unetched, actual size)

EVALUATION OF INTERNAL SHRINKAGE IN CAST STEEL

Fig. 6B



RADIOGRAPHIC IMAGE OF DENDRITIC SHRINKAGE IN CAST STEEL 1% INCHES THICK. EVALUATION IS SHOWN IN FIG. 7B.

Fig. 7A

EVALUATION OF FIG. 7A

Severity level of shrinkage shown in Fig. 7A compares with the following:

ASTM—E—446 — Type CB — Grade 5 ASTM—E—186 — Not applicable, too thin MIL—R—11469 — Type C — Std. 3



Macrograph of casting cross section — AA, shown in Fig 7A, revealing severity and location of the shrinkage condition. (unetched, actual size)

EVALUATION OF DENDRITIC SHRINKAGE IN CAST STEEL 1% INCHES THICK.

Fig. 7B




Radiographic image of dendritic shrinkage in $2\frac{1}{2}$ " thickness of steel. Severity level shown compares with the following:

ASTM-E-446 - Not applicable, too thick

ASTM-E-186 - Type C - Std. 4


MIL-R-11469 -- Type C -- Std. 3

Fig. 8A



Macrograph of casting cross section, shown in Fig. 8A, revealing severity and location of shrinkage condition. (unetched, actual size)

Fig. 8B



RADIOGRAPHIC IMAGE OF DENDRITIC SHRINKAGE IN CAST STEEL 2 INCHES THICK. EVALUATION SHOWN IN FIG. 9B.

Fig. 9A

EVALUATION OF FIG. 9A

Severity level of shrinkage shown in Fig. 9A compares with the following:

ASTM—E—446 — Exceeds Grade CB-5 ASTM—E—186 — Type 2 — Grade 5 MIL—R—11469 — Type C — Std. 4




SECTION AA

SECTION BB

SECTION CC

Macrographs of casting cross sections, shown in Fig. 9A, revealing severity and location of shrinkage condition. (unetched, actual size)

Fig. 9B



Radiographic image of sponge shrinkage in 1%" steel. Severity level shown compares with the following:


ASTM—E—446 — Type CC, Grade 4 ASTM—E—186 — Not applicable, too thin MIL—R—11469 — Type D — Std. 3



Macrograph of casting cross section-AA showing severity and location of shrinkage condition. (unetched, actual size)

EVALUATION OF SPONGE SHRINKAGE IN CAST STEEL 1½ INCHES THICK.

Fig. 10



RADIOGRAPHIC IMAGE OF SPONGE SHRINKAGE IN CAST STEEL 1½ INCHES THICK. EVALUATION INCLUDED IN FIG. 11B.

Fig. 11A

EVALUATION OF FIG. 11A


Severity level of the shrinkage shown in Fig. 11A compares with the following:

ASTM-E-446 - Type CC - Grade 5 ASTM-E-186 - Not applicable, too thin MIL-R-11469 - Type D - Std. 3




Macrograph of casting cross section AA, shown in Fig. 11A, revealing severity and location of the shrinkage condition. (unetched, actual size)

EVALUATION OF SPONGE SHRINKAGE IN CAST STEEL 11/2 INCHES THICK.



Radiograph of a 3" hot tear in cast steel 2½ thick (Radiation angle 20°)



Same hot tears as above but radiation was more parallel with the tear. Severity evaluation shown in Fig. 12B.

Fig. 12A

EVALUATION OF FIG. 12A

Severity level of the tear shown in Fig. 12A compares with the following:

ASTM-E-446 - Not applicable, too thick


ASTM-E-186 - Level 4 MIL-R-11469 - Std. 4



Macrograph of casting cross section AA, shown in Fig. 12A, revealing severity and location of the tear. (unetched, actual size)

EVALUATION OF HOT TEAR IN CAST STEEL 21/2 INCHES THICK.

Fig. 12B



Radiograph of a 5" hot tear in cast steel 21% inches thick. Severity level is as follows:

ASTM-E-446 - Not applicable, too thick

ASTM-E-186 - Level 5

MIL-R-11468-Std. 5

EVALUATION OF HOT TEAR IN CAST STEEL 21/2 INCHES THICK.

Fig. 13A



Macrograph of casting section AA shown in Fig. 13A, revealing cross sectional extent of the tear. (unetched, actual size)


EVALUATION OF HOT TEAR IN CAST STEEL 21/2 INCHES THICK.

Fig. 13B

ALUMINUM CASTING FLAWS

This edition of the report is updated to include 22 figuresactual photographs- of the various aluminum casting flaws under study. The pictures will permit engineers and technicians to get a realistic perception for material integrity and flaw classification in these thickness ranges of aluminum.

GAS HOLES



Actual Size Radiograph - Material Thickness 5/16"
Neets Std. 4 of ASTH E-155



Macrograph of Cross Section AA Exposing the Flaw 4X Magnification- Unetched

GAS HOLES



Actual Size Radiograph - Material Thickness 5/16" Meets Std. 7 of ASTM E-155




Macrograph of Cross Section AA Exposing the Flaw 4X Magnification- Unetched

GAS POROSITY - ROUND




Actual Size Radiograph - Material Thickness 1/4"
Neets Std. 2 of ASTN E-155



Micro-Radiograph of a .025" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Porous Condition at 10% Hagnification.



Macrograph of Cross Section AA (Fig. 2A) Showing Std. 2 Porosity at 4X Magnification. Unetched



Micrograph of Cross Section AA (Fig. 2A) Showing the Porous Condition at 100X Magnification - Kellers Etch.




Actual Size Radiograph - Material Thickness 3/8"
Neets Std. 4 of ASTM E-155



Micro-Radiograph of a .025" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Porous Condition at 10X Magnification.



Macrograph of Cross Section AA (Fig.3A) Showing Std.4 Porosity at 4X Magnification - Unetched.



Micrograph of Cross Section AA (Fig. 3A) Showing the Porous Condition at 100X Magnification - Kellers Etch.



Actual Size Radiograph - Material Thickness 1/4"
Meets Std. 6 of ASTM E-155




Micro-Radiograph of a .025" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Porous Condition at 10X Magnification.

EVALUTION OF GAS POROSITY-ROUND IN CAST ALUMINUM


Figure 4A




Macrograph of Cross Section AA (Fig. 4A) Showing Std.6 Porosity at 4X Magnification - Unetched



Micrograph of Cross Section AA (Fig.4A) Showing the Porous Condition at 100X Magnification-Kellers Etch.



Actual Size Radiograph - Naterial Thickness 1/4"& 3/8" Neets Std. 3 of ASTM E-155



Micro-Radiograph of a .027" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Porous Condition at 10X Magnification.



Macrograph of Cross Section AA (Fig.5A) Showing Std. 3 Porosity at 4X Magnification-Unetched.



Micrograph of Cross Section AA (Fig.5A) Showing the Porous Condition at 100X Magnification-Kellers Etch.




Actual Size Radiograph - Material Thickness 1/2"
Meets Std.6 of ASTM E-155



Micro-Radiograph of a .020" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Porous Condition at 10X Magnification.




Macrograph of Cross Section AA (Fig.6A) Showing Std. 6 Porosity at 4X Magnification-Unetched.




Micrograph of Cross Section AA (Fig.6A) Showing the Porous Condition at 100X Magnification-Kellers Etch.

GRAIN BOUNDARY SHRINKAGE



Actual Size Radiograph - Material Thickness 3/8"
This Condition is not included in ASTM E-155. It
Appears Similar to, and Compares with Std.4 of Gas Pqrosity-Elongated.




Micro-Radiograph of a .030" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Shrinkage Condition at 10X Magnification.

EVALUATION OF GRAIN BOUNDARY SHRINKAGE IN HIGH STRENGTH CAST ALUMINUM.

GRAIN BOUNDARY SHRINKAGE



Macrograph of Cross Section AA (Fig.7A). No Evidence of the Shrink Condition is Visible at 4X Magnification - Unetched.



Micrograph of Cross Section AA (Fig.7A) Showing the Shrink Condition at 100X Magnification - Kellers Etch.

EVALUATION OF GRAIN BOUNDARY SHRINKAGE IN HIGH STRENGTH CAST ALUMINUM.

SHRINKAGE - CAVITY



Actual Size Radiograph - Material Thickness 1/4"
Neets Std.3 of ASTM E-155



Macrograph of Cross Section AA Exposing the Flaw-4X Magnification - Unetched. Small Pores are Gas Porosity.

EVALUATION OF CAVITY TYPE SHRINKAGE IN CAST ALUMINUM

SHRINKAGE - CAVITY



Actual Size Radiograph - Material Thickness 1/4"
Meets Std.7 of ASTM E-155




Macrograph of Cross Section AA Exposing the Flaw- 4X Magnification - Unetched. Small Pores are Gas Forosity.

EVALUATION OF CAVITY TYPE SHRINKAGE IN CAST ALUMINUM



Actual Size Radiograph - Material Thickness 7/8" Meets Std.4 of ASTM E-155




Micro-Radiograph of a .023" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Shrinkage Condition at 10X Magnification.


EVALUATION OF SPONGE SHRINKAGE IN CAST ALUMINUM

Figure 10A






Macrograph of Cross Section AA (Fig.10A) Showing Std. 4 Shrinkage at 4X Magnification - Unetched.




Micrograph of Cross Section AA (Fig. 10A) Showing the Shrinkage Condition at 100X Magnification - Kellers Etch.

EVALUATION OF SPONGE SHRINKAGE IN CAST ALUMINUM



Actual Size Radiograph - Material Thickness 5/16" Meets Std.7 of ASTM E-155




Micro-Radiograph of a .025" Thick Specimen Adjacent to Cross Section AA Showing a Single Layer View of the Shrinkage Condition at lox Magnification.

EVALUATION OF SPONGE SHRINKAGE IN CAST ALUMINUM



Macrograph of Cross Section AA (Fig.11A) Showing Std. 7 Shrinkage at 4X Magnification - Unetched.



Micrograph of Cross Section AA (Fig.11A) Showing the Shrinkage Condition at 100X Magnification - Kellers Etch.

EVALUATION OF SPONGE SHRINKAGE IN CAST ALUMINUM

FOREIGN MATERIAL - LESS DENSE



Actual Size Radiograph - Material Thickness 5/16" Meets Std. 7 of ASTM E-155"



Macrograph of Cross Section AA Exposing the Flaw 4X Magnification - Unetched



Macrograph of Cross Section BB Exposing the Flaw 4X Magnification - Unetched

EVALUATION OF FOREIGN MATERIAL IN CAST ALUMINUM

FOREIGN MATERIAL-LESS DENSE



Actual Size Radiograph - Material Thickness 5/8"
Neets Std. 8 of ASTN E-155



Macrograph of Cross Section AA Exposing the Flaw 4X Magnification - Unetched

EVALUATION OF FOREIGN MATERIAL IN CAST ALUKINUM

DISTRIBUTION LIST

AUDRESSEE	NO. OF COPIES
Commander U.S. Army Armament Command ATTN: DRSAR-Q, Mr. J. Obren DRSAR-QAE, Mr. D. Spears DRSAR-PPW-IR, Mr. E, Case Rock Island, IL 61201	1 1
Commander Rock Island Arsenal ATTN: SARRI-R, Mr. W. Kisner SARRI-LEQ, Mr. J. Hausman SARRI-R, Mr. W. McHenry Rock Island, IL 61201	1 1
Commander Watervliet Arsenal ATTN: SARWV-PPI, Hr. L. A. Jette SARWV-QA, Hr. J. Miller SARWV-QAS, Mr. J. Honaghan Watervliet, NY 12189	1
Commander Picatinny Arsenal ATTN: SARPA QA-X, Mr. Fitzsimmons SARPA-VC 2, Mr. T. M. Roach SARPA-QA-T-T, Mr. D. Stein Hr. H. HcAlogn Dover, NJ 07801	1
Commander Frankford Arsenal ATTN: SARFA-QAF-R. Mr. J. Braverman SARFA-K3300, Mr. G. Norwitz SARFA-K-4000, Mr. H. Sokolowski SARFA-QAA-Q, Mr. J. Barr Philadelphia, PA 19137	1 1 1
Commander Edgewood Arsenal ATTN: Mr. W. E. Montanary, G., Program Division SAREA-PATM, Dr. W. J. Maurits Abandeen Proving Ground MD 21005	1

ADDRESSEE	NO. OF COPIES
Commander U.S. Army Electronics Command ATTN: DRSEL-QM DRSEL-PAE, Mr. S. Alster Fort Monmouth, NJ 07703	1
Commander U.S. Army Missile Command ATTN: DRSMI-QLC, Mr. Kenneth E. Parr Mr. Knowlen Knowles Redstone Arsenal, AL 35809	1
Commander Harry Diamond Laboratories ATTN: DRXDO-PP, Mr. Hoke DRXDO-EDE, Mr. Benjamin F. Willis 2800 Powder Mill Road Adelphi, MD 20783	1
Commander U.S. Army Tank-Automotive Research & Development Command ATTN: DRDTA-RKA DRDTA-JE, Mr. Gamache Warren, Michigan 48090	2 4 1
Commander U.S. Army Tank-Automotive Materiel Readinass Command ATTN: DRSTA-OA UNSTA-G Warren, MI 48090	1
Commander U.S. Army Aviation Systems Command ATTN: DRSAV-L DRSAV-LE, Mr. J. T. Conroy P. O. Box 209 St. Louis, MO 63166	1
Commander U.S. Army Test & Evaluation Command ATTN: DRSTE-TAA DRSTE-TO-P, Mr. A. Baldridge DRSTE-ME, Mr. S. Wise Aberdeen Proving Ground MD 21005	1 1 1

ADDRESSEE	NO. OF COPIES
Commander Aberdeen Proving Ground ATTN: STEAP-MT-M STEAP-HT-G, Mr. R. L. Huddleston Aberdeen Proving Ground, MD 21005	1
Commander Dugway Proving Ground ATTN: STEDP-PC Dugway, UT 84622	1
Commander Jefferson Proving Ground ATTN: STEJP-TD Hadison, IN 47250	1
Commander U.S. Army Tropic Test Center ATTN: STETC-TD-T, Drawer 942 Fort Clayton, CZ	1
Commander U.S. Army White Sands Missile Range ATTN: STEWS-TE-PM White Sands Missile Range, NA 88002	1
Commander Yuma Proving Ground ATTN: STEYP-MP, Mr. Unl Yuma, AZ 85364	1
Commander U.S. Army Troop Support Command ATTN: DRSTS-Q 4300 Goodfellow Boulevard St. Louis, MO 63120	1
Commander U.S. Army Mobility Equipment Research & Bevelorment Command ATTN: DRXFB-QA, Mr. J. K. Mauzy DRXFB-EM, Mr. S. Levine DRXFB-RM, Mr. E. York Fort Belvoir, VA 22060	1 1 1
Commander U.S. Army Natick R&D Command ATTN: DRXNM-EM, Nr. S. Werkowski DRXNM-GE, Mr. N. Budnick Kansas Street Natick, NA 01762	1

ADDRESSEE	NO. OF COPIES
Director Army Materials and Mechanics Research Center ATTN: DRXMR-CT DRXMR-MI, Mr. G. A. Darcy DRXMR-RA, Mr. F. Valente DRXMR-EM, Mr. T. DeSisto DRXMR-X, Dr. E. S. Wright ORXMR-PP, Mr. J. O'Connor Mr. M. Cheney Watertown, MA 02172]]]]
PM. Selected Ammunition Picatinny Arsenal Dover, NJ 07801	1
PM. Aircraft Survivability Equipment U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, CH-47 Modernization Program U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, COBRA U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, Iranian Aircraft Program U.S. Army Aviation Systems Command St. Louis, MO 63166	
PM, Heavy Lift Helicopter U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, Army Tactical Communications Systems U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PI4, Army Tactical Data Systems U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PM. Mortar/Artillery Locating Radars U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1

AUURESSEE	NO. OF COPIES
PM, Multi-Service Communications Systems. U.S. Army Electronics Command Ft. Honmouth, NJ 07703	1
PM. Navigation Control Systems U.S. Army Electronics Command Building 2525	
Ft. Honmouth, NJ 07703	1
PM. Remotely Monitored Battlefield Sensor System U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PM, Dragon	
U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM, Hawk	
U.S. Army Hissile Command Redstone Arsenal, AL 35809	1
PM, HELLFIRE Missile System	
U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM. LANCE	
U.S. Army Missile Command Redstone Arsenal, AL 35809	1
·	•
PM, Pershing U.S. Army Missile Command	
Redstone Arsenal, AL 35809	1
PM, Precision Laser Designators	
U.S. Army Missile Command	
Redstone Arsenal, AL 35809	1
PM, 2.75" Rocket System	
U.S. Army Missile Command	_
Redstone Arsenal, AL 35809	1
PM, TOW	
U.S. Army Missile Command Padstone Arsonal Al 35800	,

ADDRESSEE	NO. OF COPIES
PM. 1-1/4 Ton Commercial Truck Systems U.S. Army Tank-Automotive Materiel Readiness Command MAMP, Bldg. 2 Warren, Michigan 48090	1
PH, FAMECE Ft. Belvoir, VA 22060	,
PM. Heavy Equipment Transporter U.S. Army Tank-Automotive Nateriel Rediness Command Warren, Michigan 48090	1
PH, M60 Tank Development 28150 Dequindre Warren, MI 48092	1
PH, Advanced Attack Helicopter U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM. Mechanized Infantry Combat Vehicle U.S. Army Tank-Automotive Materiel Rediness Command 28150 Dequindre Warren, WI 48092	1
PM, Mobile Electric Power 7500 Backlick Road Springfield, VA 22150	1
PH, Munitions Production Base Modernization and Expansion Picatinny Arsenal Dover, NJ 07801	1
PH, PATRIOT U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM, Satellite Communications Ft. Monmouth, NJ 07703	1
PM, SANG ATTN: AMCPM-NG 5001 Eisenhower Avenue Alexandria, VA 22333	1
PM, Training Devices Naval Training Equipment Center Onlando El 32813	1

ADDRESSEE	NO. OF COPIES
PM, Utility Tactical Transport Aircraft System U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, XM-1 Tank System 28150 Dequindre Warren, MI 48092	. 1
PM, Stinger U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM, Advanced Scout Helicopter U.S. Army Aviation Systems Command St. Louis, MO 63166	1
PM, Special Electronic Mission Aircraft (SEMA) Materiel Rediness U.S. Army Aviattion Systems Command St. Louis, MO 63166	1
PH, Single Channel Ground and Airberne Radio Subsystem U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PM, Signal Intelligence/Electronic Markare (SIGINT/EW) Hateriel Readiness U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PM, High Energy Laser System U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM, KUWAIT U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PM, US ROLAND U.S. Army Missile Command Redstone Arsenal, AL 35809	1
PH, VIPER U.S. Army Missile Command Redstone Ar: nal, AL 35809	1

ADDRESSEE	NO. OF COPIES
PM, Improved TOW Vehicle (ITV) U.S. Army Tank-Automotive R&D Command Warren, MI 48090	1
PM, M60 Tank Production 28150 Dequindre Warren, MI 48092	1 2
PM. Amphibians and Watercraft U.S. Army Troop Support Command 5300 Goodfellow Boulevard St. Louis. MO 63120	1
PM, Army Container Oriented Distribution System U.S. Army Material Development & Readiness Command 5001 Eisenhower Avenue Alexandria, VA 22333	1
PH. Chemical Demilitarization and Installation Restoration Aberdeen Proving Ground, MD 21010	1
PH, DCS (Army) Communications Systems Ft. Monmouth, NJ 07703	- 1
PM, Nuclear Munitions Picatinny Arsenal Dover, NJ 07801	1 .
PM, Automatic Test Support Systems U.S. Army Electronic Command Ft. Monmouth, NJ 07703	1
PM, FIREFINDER U.S. Army Electronics Command Ft. Monmouth, NJ 07703	1
PM, M113/M113Al Family of Vehicle Readiness U.S. Army Tank-Automotive Materiel Readiness Command MAMP, Bldg. 2	•
PM. SMOKE Aberdeen Proving Ground, MD 21005	1
PM, Army Gun Air Defense Systems U.S. Army Armament Command Rock Island, IL 61201	1

ADDRESSEE	NO. OF COPIES
PM, Cannon Artillery Weapons Systems Picatinny Arsenal Dover, NJ 07801	1
PH. M110E2 8" Howitzer U.S. Army Armament Command Rock Island, IL 61201	1
PM. Safeguard Hunitions Picatinny Arsenal Dover, NJ 07801	. 1
Defense Documentation Center ATTN: DDC-TC Cameron Station 5010 Duke Street	12
Alevandria VA 22314	

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered) READ INSTRUCTIONS REPORT DOCUMENTATION PAGE BEFORE COMPLETING FORM T. REPORT HUMBER 2. BOYT ACCESSION NO. 3. RECIPIENT'S CATALOG NUMBER 12256 4. YITLE (and Subliste) S. TYPE OF MEPORT & PERIOD COVERED Development of Quality Assurance Training Manual to Assist in Establishing Soundness Requirements for Aluminum and Steel Castings 4. PERFORMING DRG.-REPORT NUMBER 7. AUTHORES B. CONTRACT OR GRANT NUMBER(e) Walter F. Wulf and Melvin V. Phytila Salvatore B. Catalano and Don Matichuk S. PERFORMING ORGANIZATION NAME AND ADDRESS IO. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS U.S. Army Tank-Automotive Research & Development Command Warren, Michigan 48090 11. CONTROLLING OFFICE HAME AND ADDRESS 12. REPORT DATE August 1978 13, NUMBER OF PAGES 14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office) 18. SECURITY CLASS, (of this report) Unclassified 184. DECL ASSIFICATION/DOWNGRADING IS. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, Il Cilierunt from Report) IS. SUPPLEMENTARY NOTES 18. KEY WORDS (Continue on reverse side it necessary and identity by block number)

Samples of aluminum and steel casting flaws most commonly experienced in production were selected to be radiographed in order to develop quantitative and descriptive picture images of various radiographic reference standards. Graphic illustrations of flaw size and flaw distribution for various radiographic reference standards were depicted by using radiographs and associated cross-sectional photo-macrographs. These graphic illustrations of radiographic levels of acceptance will provide meaningful design criteria for establishing (continued on reverse)

DD FORM 1473 THE EDITION OF I NOV 65 IS OBSOLETE

20. ABSTRACT (continued)

realistic standards of acceptance for new material applications. This report also furnishes operational guidance to quality assurance and realiographic personnel in their normal on-the-job duties.